

Product Change Notification / SYST-05BLVU646

Date:

06-Feb-2014

Product Category:

16-Bit - Microcontrollers and Digital Signal Controllers

PCN Type:

Silicon Die Revision

Notification Subject:

ERRATA - dsPIC33EPXXXGP50X, dsPIC33EPXXXMC20X/50X AND PIC24EPXXXGP/MC20X Errata Silicon Die Revision Addition

Affected CPNs:

SYST-05BLVU646_Affected_CPN_02062014.pdf SYST-05BLVU646 Affected CPN 02062014.csv

Notification Text:

SYST-05BLVU646

Microchip has released a new DeviceDoc for the dsPIC33EPXXXGP50X, dsPIC33EPXXXMC20X/50X AND PIC24EPXXXGP/MC20X Errata of devices. If you are using one of these devices please read the document located at dsPIC33EPXXXGP50X, dsPIC33EPXXXMC20X/50X AND PIC24EPXXXGP/MC20X Errata.

Notification Status: Final

Description of Change: Addition of silicon die revision A8.

Impacts to Data Sheet: None

Reason for Change: To Improve Manufacturability

Change Implementation Status: Complete

Estimated First Ship Date: 03 Mar 2014

Markings to Distinguish Revised from Unrevised Devices:Traceability Code

Attachments	:			
dsPIC33EPXXX	GP50X, dsPIC33EPXXXMC20X	/50X AND PIC24E	PXXXGP/MC20X Errat	a
_	our local <mark>Microchip sales offic</mark>	with questions or	concerns regarding this	notification.
Terms and Cond	itions:			
website at http:	ange your product/process cha //www.microchip.com/PCN s n select a profile option from th	ign into myMICRO	CHIP to open the myMIC	
here to go to <mark>m</mark>	ure offer or information emails crochipDIRECT and login, then the check the box that states "Futu	n click on the "My a	account" link, click on "U	lpdate