



Eaton  
Electronics Division  
5735 W. Las Positas Blvd #100  
Pleasanton, CA 94588  
www.eaton.com/elx

## Product Change Notice

PCN#: EE-PCN16030

Aug 09, 2016

### CLASSIFICATION OF CHANGE:

End of Life.

### DESCRIPTION OF CHANGE:

Discontinuance of product supply.

### REASON FOR CHANGE:

Product Line has reached end of life cycle.

There is no direct recommended replacement available.

Please review Eaton's [MPI4040R1-R](#), [SD14-R](#) and [MPI2520R1-R](#) for recommended alternatives.

### EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

Not applicable

### PARTS FAMILIES AFFECTED:

SD3814-R47-R	SD3814-8R2-R	SD3814-820-R
SD3814-R82-R	SD3814-100-R	SD3814-101-R
SD3814-1R2-R	SD3814-150-R	SD3814-151-R
SD3814-1R5-R	SD3814-220-R	SD3814-221-R
SD3814-2R2-R	SD3814-330-R	SD3814-331-R
SD3814-3R3-R	SD3814-470-R	SD3814-471-R
SD3814-4R7-R	SD3814-680-R	SD3814-681-R
SD3814-6R8-R		

### TIME SCHEDULE:

Effective Aug 9, 2016.

### LAST TIME BUY SCHEDULE:

Before Oct 9, 2016

### ISSUED BY:

Product Manager: Jenny Li

### CONTACT INFORMATION:

For questions or comments, please contact your local [Eaton sales representative](#).